## **TABLE OF CONTENTS**

Ta	ble of C		į			
A	cknowle		vi			
Li	st OF Al	•••	vi			
Li	st OF Fi	•••	ix			
Li		Х				
CI	napter 1		1			
1.0	1.0 Introduction.					
1.1 Statement of the Problem						
1.:	2 Purpo	se of Study		8		
1.3	3 Resea	arch Questions		8		
1.4	4 Scope	and Limitations		8		
1.	5 Metho	dology		9		
1.6	6 Docur	nent Flow		9		
1.7	7 Conclu	usion		10		
Cł		11				
2.0		11				
2.1		12				
2.2		14				
2.3	3 Issues	in Raising Speed to 160-200 kmph		16		
	2.3.1	Segregation of Passenger and Freight Traffic	•••	16		
	2.3.2	Lack of Financial Resources	•••	17		
	2.3.3	Over Saturated Trunk Routes	•••	20		
	2.3.4	Rolling Stock for Semi-High Speed	•••	21		
	2.3.5	Organisational Re-structuring		24		
	2.3.6	Under-Recovery of Cost in Passenger Business		26		
	2.3.7	Inadequately Defined Mission and Objectives		27		
	2.3.8	Trespassing on Railway Tracks		28		
	2.3.9	Large Number of Level Crossings		29		
	2.3.10	Monitoring of Weather Conditions	•••	31		
	2.3.11	Automatic Train Protection (ATP) System	•••	32		
	2.3.12	Upgradation of Track Infrastructure		34		
2	locuos	in Comi High Chood Poil		36		

					2000
	Concl	•••	37		
Ch		38			
3.0	Introd		38		
3.1	Profile		39		
3.2	Identi	Identification and Finalisation of the Barriers			41
3.3	Interp	retative S	Structural Modelling (ISM)		43
	3.3.1 Steps Involved in ISM				45
		3.3.1.1	Structural Self Interaction Matrix (SSIM)		46
		3.3.1.2	Reachability Matrix (RM)		47
		3.3.1.3	Level Partition of Reachability Matrix	•••	49
		3.3.1.4	MICMAC Analysis	•••	49
		3.3.1.5	Canonical Matrix		50
		3.3.1.6	Digraph and ISM Model		51
	3.3.2	Advanta	ages of ISM		51
	3.3.3	Limitati	ons of ISM	•••	53
3.4	Concl	lusion		•••	53
Ch	apter 4	- ISM M	lodelling of Barriers of Semi-High Speed		55
4.0	Introd	luction			55
4.1	Discu	ssion on	Barriers		55
	4.1.1 Lack of Financial Resources				55
	4.1.2	Organisational Structure		56	
	4.1.3	Inadequately Defined Mission and Objectives			57
	4.1.4	Over Saturated Trunk routes			58
	4.1.5	Lack of High Speed Locomotives/Coaches/Train Sets			59
	4.1.6		ograded Track and Bridge Infrastructure		59
	4.1.7	Lack of	ATP Based Signalling System		60
	4.1.8	Lack of Weather Monitoring System			60
	4.1.9	Lack of Public Awareness Regarding			61
		Trespa	ssing/Encroachment on Railway Tracks		
	4.1.10	Non-Av	vailability of Automatic Public Announcement		61
		System	n on Stations		
	4.1.11	Un-pro	tected Tracks (Large Number of Level		62
		ngs and Non-Fencing of Tracks)		00	
4.2		Development of ISM Model			62
	4.2.1		red Self-Interaction Matrix of Barriers	•••	64
	422	Reacha	ability Matrix of Barriers		66

	4.2.3	Level Partition of Reachability Matrix		69
	4.2.4	ISM Model Formulation		71
4.3	MICM		76	
4.4	Discus		78	
4.5	Conclusion			80
Ch		81		
5.0	Introduction			81
5.1	Concl		84	
5.2	Recor	nmendations		85
5.3	Contri	bution of the Study		86
5.4	Limita	tions		86
5.5	Concl	usion		87
References				
Rih		92		